Annexure- D

BUILDING SAFETY CERTIFICATE

Ref No.2025-26 Dated:**24 /08/2026**

It is certified that the existing building **SNBP's International school** at **Manjri Tal. Haveli Dist. Pune State - Maharashtra** is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (01)	Block (02)	Block (04)	Block (05)	Block (06)
No. of Floor (s) in the Block	Ground floor + 03 Upper floor	Ground floor + 03 Upper floor	--	--	--

The building is owned/occupied by **SNBP's International school** have complied with the building safety requirements in accordance with National Building code Rules, and verified by the officers concerned **Mr.Milind Bansode, structural Engineer** on **18/08/2026** in the presence of **MS Madhu Dudia , Principal SNBP's International School Manjri, Dist. Pune** and that the building / premises is fit for occupancy for running school with effect from **24/08/2026** for a period of **01 year** in accordance with rule and subject to compliance of the specific conditions as appended.

1. **Nil**
2. Nil

Issued on **24/08/2026** at **Manjri, Dist. Pune** by

*Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

BANSODE M.B.
M.Tech (Civil) / I.I.V, M.I.S.E., A.M.I.E,
Structural Engineer Regn. No. 670-B (PMC)
Structural Engineer STATE/R/2023/APL/65829
Chartered Engineer IF (India) AM 1747528
Architect & Engineer ENG/37/2017(PMRDA)

Signature with Seal: _____

Name: Mr. Milind Bansode

Designation: Structural Engineer

Name & Address of Department/ Office: Office L-110, Mega Center, Behind Noble Hospital Hadapsar, Pune-411028